



Shore Power Solutions  
 PO Box 143  
 Grasonville, MD 21638


4108277810

# Invoice

Date: 9/9/2019  
 Invoice #: 3432

**PAID**  
 09/09/2019

Bill To



E-mail	Technician
admin@shorepowersolutions.net	SSS

Terms		Boat/Equip Info		P.O. No.	Engine Model Info	Serial Number- PORT	Serial Number- STBD	
Due on receipt		SuperDuty		Service	Cummins QSM 11			
Item	Tech	Serviced	Description			Quantity	Rate	Amount
Parts			Rebuild 4 racor filter assemblies					
Labor			Parts				240.00	240.00T
			Labor			3	125.00	375.00
Labor			Replace both transmission filters with Baldwin					
			Labor and parts				100.00	100.00
Labor			Valve adjustment on both mains					
			Labor			4	125.00	500.00
Labor			Service aftercoolers					
			Labor and parts				3,500.00	3,500.00
Parts			Replace zines					
Labor			Parts				96.00	96.00T
			Labor			1	125.00	125.00
Parts			Replace impellers					
Labor			18000K			2	239.99	479.98T
			Labor			1	125.00	125.00
			cash: 15% off of labor					

<b>Total</b>
<b>Payments/Credits</b>
<b>Balance Due</b>



Shore Power Solutions  
 PO Box 143  
 Grasonville, MD 21638

4108277810

# Invoice

Date: 9/9/2019  
 Invoice #: 3432

**PAID**  
 09/09/2019

Bill To



E-mail	Technician
admin@shorepowersolutions.net	SSS

Terms	Boat/Equip Info	P.O. No.	Engine Model Info	Serial Number- PORT	Serial Number- STBD
-------	-----------------	----------	-------------------	---------------------	---------------------

Due on receipt	SuperDuty	Service	Cummins QSM 11		
----------------	-----------	---------	----------------	--	--

Item	Tech	Serviced	Description	Quantity	Rate	Amount
Labor			<p>Notes for Labor:</p> <p>8/21/2019            Removed valve cover and performed valve adjustments on both engines. Found some rust on rockers while adjusting. Took pictures and notified customer. Reinstalled valve covers. Removed old impellers and replaced with new. Topped off oil level. Removed racor bowl assemblies; cleaned and resealed. Primed fuel system and ran engine. Checked for leaks and cleaned up.</p> <p>8/26/2019            Removed aftercoolers from both engines. Cleaned collars and tubes at shop to be reinstalled.</p> <p>8/29/2019            Drilled and helicoiled one bolt hole in aftercooler. Reinstalled aftercoolers in both engines with new gaskets and seals. Installed collars and pipes. Installed zincs. Ran both engines and checked for leaks.</p> <p>Discounted applied            Sales Tax</p>			
					-589.94	-589.94
					6.00%	48.96

Credit Card Processing is subject to 3% fee. Invoice term will be due upon completion of work. After 30 days, a 10% fee will be added, 20% after 60 days, etc. All parts warranty are subject to manufacture policy. Parts and materials will remain property of Shore Power Solutions until payment in full is received.

<b>Total</b>	\$5,000.00
<b>Payments/Credits</b>	-\$5,000.00
<b>Balance Due</b>	\$0.00