


- NOTES:
- 1) MOTOR MOUNTING FLANGE MUST FACE AFT AT 90°
 - 2) INSTALL TUBE AFTER HULL HAS BEEN SAND COATED AND BEFORE BULK LAY UP IS APPLIED
 - 3) BULK LAY-UP IS TO OVERLAP BOW THRUSTER TUBE A MINIMUM OF 8 INCHES

		TITLE: BOW THRUSTER INSTALLATION			
MODEL	450DA	DRAWN BY	R. TAVARES	ECN REV. NO.	
DATE	3-31-97	CHECKED BY	RT	ECN NO.	
PLANT REV. NO.		APPROVED BY	kw	DRAWING NO. 04-005	